

STS

750 Corporate Woods Parkway, Vernon Hills, IL 60061 T 847.279.2500 F 847.279.2510 www.sts.aecom.com

EPA Region 5 Records Ctr.

September 24, 2008

Mr. Steven Faryan, On-Scene Coordinator U.S. Environmental Protection Agency – Region 5 77 W. Jackson Boulevard Chicago, IL 60604

Re: Gas Probe ML-6 Investigation

Mallard Lake Landfill AOC RCRA Docket 7003-5-08-001 STS Project No. 200704805

Dear Mr. Faryan:

As discussed in our meeting on September 18, 2008, STS is submitting a revised plan for investigating the nature extent of combustible gas detected in the vicinity of probes ML-6i and GPT-8. The plan has been amended to include additional investigation locations as requested by Mr. Om Patel of Weston Solutions, Inc. (Weston). The proposed investigation summarizes the approach to identifying the source and the extent of gas migration in the vicinity of probes ML-6i and GPT-8. As previously discussed, several potential sources of combustible gas may exist. The potential sources of gas which should be evaluated include the following:

- · The sanitary sewer force main;
- The Mallard North Landfill;
- The Mallard Lake Landfill; and
- Biogenic and/or swamp gas from decomposition of organic matter.

However, swamp or biogenic gas would not be likely to contain volatile organic compounds (VOCs) which were identified during the previous summa canister monitoring conducted during July 2008. Thus, even if the methane is the result of biogenic gas, it is apparent that a source of VOCs must also exist.

1.0 ML-6i Investigation Plan

Due to the number of potential sources, STS believes that it will be more productive to initiate the investigations in the vicinity of ML-6i and to work out radially to map the extent of combustible gas and identify the source of the gas migration. Figure 1 provides a probe location diagram depicting the locations of proposed monitoring probes in the area surrounding ML-6. As discussed in our phone conversations, the investigation has initially been restricted to the Forest Preserve District of DuPage County (FPDDC) property in order to minimize any delays associated with negotiating access to adjoining properties. If necessary, the investigations may be expanded to adjacent properties based on the field characterization of the extent of the gas. The investigation of the offsite areas can commence once signed access agreements have been obtained. As discussed in the September 18, 2008 meeting, STS proposes that the extent of the combustible gas be investigated utilizing the following tools:

 Geoprobe borings will be advanced to install gas monitoring probes in order to investigate the extent of gas migration;

- 2) Shallow soil gas monitoring will be conducted along the alignment of the sanitary sewer force main in order to evaluate potential gas migration within granular backfill; and
- 3) Finally, gas monitoring probes which indicate the presence of combustible gas and/or elevated photoionization detector (PID) readings will undergo summa canister analyses for VOCs.

The proposed investigation procedures are described in greater detail in the subsequent paragraphs.

1.1 Gas Probe Installation

Figure 1 depicts the proposed investigation in the vicinity of ML-6. A total of eleven geoprobe borings will be advanced around probe ML-6 to delineate the extent and the source of the combustible gas. The proposed probe locations have been limited to FPDDC property so that the scope may be quickly implemented without having to negotiate off-site access agreements. It is anticipated that the investigations will be conducted using a track mounted GeoprobeTM rig. The holes will be advanced to a depth sufficient to attain a minimum boring bottom elevation of at least 750 ft mean sea level (msl) (approximately 45 ft below ground surface [bsg] in the vicinity of ML-6 and approximately 14 feet below the mean pool elevation on the West Branch of the DuPage River). This will enable screening of the vertical interval where the methane was identified at ML-6i (screen interval from 750.5 to 769.7 ft. msl) and will also enable the boring to be advanced the lowest observed piezometric surface for the W1/W2 granular unit. The borehole will be sealed around the GEM 500 inlet using a plastic or rubber grommet after every geoprobe run (approximately every 4 ft) to screen for the presence of methane. The screen interval of the probe will be placed such that the screen zone of the probe extends at least 4 ft above the 1st gas detection interval and approximately 10 ft below this interval (i.e., the interval will be spanned using a 15 ft screen interval). The probe screen interval will be backfilled with sand and a granular bentonite seal will be placed above the flush mount screen and will be hydrated. A sealed flush mount protector casing will be installed to provide a surface completion.

Probe ML-6i was drilled to a total depth of 41.1 ft from a surface elevation of approximately 793.0 ft msl. Probe ML-6i was completed with a 20 ft screen interval extending from approximately 752 ft to 772 ft msl. Thus, the probe is completed across an interval extending from approximately 10 feet below the river bed to approximately 8 feet above the river mean stage pool elevation (approx 764 ft msl).

As shown in Figure 1, probes ML-13 and ML-15 will be located on relatively steep slopes along the southeast side of the West Branch of the DuPage River. STS proposes that existing Mallard North Landfill monitoring wells MW-204S and MW-205 be monitored in lieu of the two additional river bank probes requested by Weston during the September 18, 2008 meeting. Well MW-204S is screened from 742.0 to 756.5 ft msl and Well MW-205 is screened from 742.9 to 757.9, thus the top of both well screens are located approximately 5 ft below the base of the West Branch of the DuPage River (estimated base elevation 762 ft msl, Mean Pool Elevation 765 ft. msl). As such, wells MW-204 and MW-205 are well positioned to identify potential gas and/or groundwater migration from the Mallard North Landfill below the river. Due to the difficult topographic conditions and the presence of the existing monitoring wells, STS believes that the western side of the area will be adequately delineated using the two additional probes ML-13 and ML-15 in combination with existing monitoring wells MW-204S and MW-205. STS also proposes that the deep monitoring well MW-204D also be screened for the presence of combustible gas, to verify that a deeper pathway does not exist below the river. The as-built construction information for the Mallard North monitoring wells MW-204S and MW-205 are provided in Attachment 1.

Several of the proposed gas probe locations (ML-13, ML-15 and ML-18) are anticipated to be located in difficult to reach areas. Even with the track mounted geoprobe rig, it may be necessary to implement some site access improvements which may include benching or slight regrading. Slope restoration work will be undertaken by BFI or their contractors, when conditions allow.

1.2 Gas Probe Monitoring

Upon completion, the probes will be monitored for the presence of CH_4 , CO_2 , O_2 and balance gas using a LandTech GEM 500. The results of the monitoring will be utilized to determine the extent of the migration, to identify the source of the methane and to evaluate the possible need to expand the characterization to adjoining properties. To assist with identifying the source of the methane, probe locations where methane is detected will also be monitored for VOC concentrations according to method TO-15. The VOC sampling will also be

conducted at probe ML-6i to assess whether the source of the VOCs is correlated to the elevated methane levels detected in this probe. Gas samples collected from probe ML-6i and other surrounding probes which indicate the presence of methane may also be analyzed for stable isotopes including carbon 13 (ς^{13} C), deuterium (ς D) and Oxygen 18 (ς^{18} O). This data will be utilized to determine whether the methane found at depth might consist of microbial gas generated from acetate fermentation (i.e., landfill gas), microbial gas from CO2 reduction or thermogenic gas (i.e., natural gas or coal gas). Refer to Coleman et al. 1993 for a more extensive discussion of isotopic gas fingerprint characterization.

1.3 Shallow Soil Gas Profiling

As discussed above, STS proposes that a shallow soil gas survey be conducted along the alignment of the sanitary sewer force main. Previous summa canister sampling conducted at the force main vent has indicated the presence of numerous VOC constituents in the gaseous emissions from the vent. The assemblage of VOC constituents at the force main vent is very similar to those identified at in the July sampling in both ML-6 and the ambient air sample obtained adjacent to ML-6. Thus, it appears that the gas release vents from the force main might act as a potential source of VOCs and methane detected at probes ML-6 and ML-6i. As such, a soil gas survey is proposed that will attempt to sample the granular backfill along the alignment of the of sanitary sewer force main. The survey will consist of driving a ½ inch diameter hole to a depth of approximately 3 ft. A sampling probe will be installed in the pilot hole and will be sealed at the ground surface using a rubber grommet with hydrated bentonite. Assuming that the granular backfill materials are encountered then the probe will be purged of approximately 3 volumes of air (approximately 0.3 L) before the gas concentrations are monitored. The soil gas samples will be analyzed using the LandTech GEM 500 (CH₄, CO₂, O₂ and balance gas) and using a multiple gas meter which includes, PID, H₂S and methane LEL. Finally, STS will also analyze the Gem 500 pump exhaust port using low level methane detection equipment. The soil gas samples will be conducted at approximately 100 ft intervals extending from the northern property boundary (i.e., adjacent to the baseball diamond) to a point due west of ML-18 (approximately 900 ft southwest of northern property boundary initial starting point). If any indications of VOCs or combustible gas are detected, the density of the sample locations will be increased by split spacing the soil gas test locations at 50 ft intervals. More samples can be added as necessary to better delineate any potential areas where methane or VOCs are encountered.

The results of the soil gas analyses may be utilized to help direct the geoprobe investigations. If elevated methane concentrations are detected at the soil gas locations, the proposed gas probes may be relocated to these areas (if within 100 ft. of the location shown in Figure 1). If the proposed soil gas probe locations (refer to Figure 1) are not within 100 ft of any location where shallow soil gas methane is detected then it might be necessary to install an additional gas probe to help characterize concentrations.

2.0 GPT-7 and GPT-8 Characterization

Pursuant to discussions during the September 18, 2008 meeting, the methane exceedance at probe GPT-8 will be investigated to determine the extent and the source of the methane exceedance. Both GPT-7 and GPT-8 were advanced to a depth of 20 ft below grade from a surface elevation of approximately 768 ft msl. Thus, both borings were advanced to approximately 748 ft msl which is deeper than the gas migration zone identified at ML-6. Saturated conditions were encountered at the base of both of the geoprobe holes. The gas concentrations encountered at probe GPT-8 appeared to be migrating above the water table but below the clay interface at a depth of approximately 8 ft. Probes GPT-7 and GPT-8 were completed across the top of the sand interval at elevations ranging between approximately 754 and 765 ft msl. STS, BFI and the FPDDC believe that this is the primary potential gas migration pathway that requires investigation.

2.1 Installation of Additional gas Probes

Pursuant to the discussions during September 18, 2008 meeting, two additional gas probes (GPT-9 and GPT-10) will be installed between the Mallard Lake Landfill and probe GPT-8. An additional probe, ML-18, will be installed within the Mallard Lake Forest Preserve approximately half way between probe ML-6i and the Mallard Lake Landfill. The approximate location of proposed probe ML-18 is presented in Figure 1.

As discussed during the meeting, the additional probes (GPT-9 and GPT-10, refer to Figure 2) will be advanced using a geoprobe rig. If possible, the probes will be advanced to depths corresponding to the base of the deepest portion of the landfill (approximately elevation of 742 ft msl). Assuming a surface elevation of 770 ft msl, it is anticipated that the geoprobe boring will be advanced approximately 38 to 40 ft. bgs in order to investigate to the depth of the landfill invert (base of waste). Attached cross-section (Figure 3) depicts the geologic conditions along the northeast side of the landfill. The cross-section indicates a relatively persistent sand unit occurring approximately between elevations 752 ft. msl and 764 ft. msl. This is the same sand unit where well GPT-8 is completed. Likewise, gas probes GPT-Is and GPT-Id are completed either within or immediately above this unit. These probes are also believed to have been historically influenced by gas migration through this sand unit.

Based on the well construction detail for well G54S (refer to Attachment 2) located along the northeast corner of the landfill, it is apparent that the deeper sand seams in the area are saturated. The hydrograph indicates that since well G54S was installed and initiated monitoring in the 1st quarter of 2001, the groundwater elevation has consistently ranged from a low of 749.6 (after 2005 drought) to a high of 756.6 ft msl. As shown by the well completion detail in Attachment 2, well G54S is screened from 740.3 to 735.3 ft. msl and at least 7 ft below the historical low groundwater table observed during the 2005 drought. No combustible gas has been observed in the headspace of well G54S during any of the monitoring rounds. Thus, the lack of an unsaturated or vadose zone combined with the fact that no gas has been observed in the deeper sand seams makes it very unlikely that any of the deeper granular units along the northeast side of the landfill could have acted as a gas migration pathway. Given review of the historical water level hydrographs, there is no reason to believe that these deeper sand units are periodically unsaturated in a manner which would allow the unit to act as a possible gas migration pathway.

Nevertheless, pursuant to USEPA's and Weston's requests during the September 18, 2008 meeting, the geoprobe investigation will seek to install GPT-9 and GPT-10 into a deeper sand unit or to the landfill base invert elevation (approximately 38 to 40 ft bgs). The geoprobe borings will be advanced and the borehole will be screened for the presence of methane after the removal of each 4 ft sample run. It is anticipated that a 4-1/4 inch inside diameter hollow stem auger may need to be advanced 10 to 15 ft to maintain the borehole at depths where collapsing granular deposits are encountered. It may not be possible to obtain discrete methane measurements within the borehole at these depths.

If any gas is detected within the shallow granular zone at the GPT-9 or GPT-10 locations, it may be necessary to install a shallow nested gas monitoring probe. Thus, it is possible that a maximum of four (two nests of 2 probes) gas probes may be installed if multiple sand units are encountered which require monitoring. The probes will be instrumented with 1 inch inside diameter, schedule 40 PVC riser pipe and 0.010 inch slotted well screen. It is anticipated that the well screen will not be any longer than 10 ft in length. The screen will be backfilled with a # 20-40 mesh gradation sand and the annular space will be backfilled with granular bentonite which will be hydrated in lifts. The probes will be completed with a locking stick-up style protector casing.

2.2 Gas Probe Monitoring

Each of the new probes described in Section 2.2 will be monitored for the presence of landfill gas related constituents and/or atmospheric gas components (i.e., CH4, CO2, O2 and balance gas). The results will be reviewed in the context of the results from GPT8 and GPT-Is to determine whether current or past landfill gas migration has occurred. If the gas at GPT-8 is isolated and does not appear to be contiguous with either the landfill or probes which have previously exhibited elevated methane levels (i.e., GPT-Is) then STS may recommend that the wells undergo gas composition testing in a manner similar to that described in section 1.2. The presence of VOCs or isotopic composition indicative of landfill gas might be used to rule out other potential sources (i.e., biogenic gas). Similarly, the data from this area will be evaluated in conjunction with the results from probe ML-18 and the other monitoring locations which will be installed in the vicinity of ML-6 in order to determine whether the gas has migrated from the south (i.e., Mallard Lake Landfill area).

If the gas at any of the probes is identified as being derived from the Mallard Lake Landfill, it will be necessary to amend the east side remedial action plan to include additional probes.

Please do not hesitate to contact us at 847-279-2500 if you have any questions or comments on the proposed work scope.

Sincerely,

Steven C. Kornder, Ph.D. Senior Geochemist

Craig S. Rawlinson, P.G. Associate Hydrogeologist

©STS 2008, ALL RIGHTS RESERVED

CC:

Eric Ballenger, BFI Jim Hitzeroth, BFI

Joe Benedict, Forest Preserve District of DuPage County

Om Patel, Weston Solutions, Inc.

Attached:


Figure 1 – ML-6 Investigation Probe Location Diagram

Figure 2 - Map Showing Locations of Probes GPT-7 and GPT-8

Figure 3 – Geologic Cross Section

Attachment 1 – Well MW-204S, MW-204D and MW-205 Well Construction Details Attachment 2 - Well G54S Well Completion Diagram, Boring Log and Hydrograph


Attachment 3 - Previous Investigation Boring Logs and Well Details




•


Mallard Lake - ML-6







Camera location 1 Google HEye alt 749 ft Streaming ||||||| 100% Pointer 41°57'33.73" N 88°08'45.31" W











EMCON

603 E. Diehl Road, #123 Naperville, Illinois 60563

LOG OF BORING MW-204 Page 1 of 2

ŀ	PROJECT NAME: Mallard North Landfill.								DATE: December 21, 1998		
	PROJECT NUMBER: 795416								DEPTH TO WATER:		
	LOCATION: Hanover Park, Illinois								TOTAL DEPTH: 50.0 feet		
	LOG	GED E	3Y:	Mike	Barinek			ર :	DRILLER/METHOD: Fox / HSA		
	DEPTH feet	SAMPLE NUMBER	BLOWS/FT.	VALUES	PROFILE	GRAPHIC LOG	SOIL CLASS	GE :	EOLOGIC DESCRIPTION	REMARKS	
		55.4			·		он	Black organ gravel	nic topsoil, moist, roots, some		
	1	SS-1	N=16				CL		noist, brown and gray, some sand	1	
		\$S-2	N=23					gray		1	
	5-	SS-3	N=39		ı			· 			
		SS-4									
	10-	SS-5	N=22							1	
	-		N≈23								
		SS-7 SS-8	N=18								
	1		N=29 N=17							-	
	_		N=17								
	20-	SS-11	N=40							-	
1.0	- -	SS-12	N=12				SM	Silty sand,	poorly sorted, subrounded,		
	25-	SS-13	N=15					gray and b	rown	-	



EMCON

LOG OF BORING MW-204 Page 2 of 2

Naperville, Illinois 60563			
PROJECT NAME: Mallard North Landfill	DATE: December 21, 1998		
PROJECT NUMBER: 795416	DEPTH TO WATER:		
LOCATION: Hanover Park, Illinois	TOTAL DEPTH: 50.0 feet		
LOGGED BY: Mike Barinek	DRILLER/METHOD: Fox / HSA		
PTH APLE APLE APLE APLE APLE APLE APLE APLE	GEOLOGIC DESCRIPTION REMARKS		

PROFILE PROF						,			
SS-18 N=15 -SS-14 N=16 -SS-15 N=47 30 -SS-16 N=28 -SS-17 N=41 -SS-18 N=24 -SS-18 N=24 -SS-19 N=51 -SS-20 N=85 -SS-20 N=85 -SS-21 N=21 -SS-22 N=10 -SS-23 N=20 -SS-24 50/6" SM Silty sand, Ian, fine to coarse grained, well some gravel Lean clay, gray, moist, some sand and gravel -SS-24 50/6" SM Silty sand, Ian, fine to coarse grained, well some gravel -SS-18 N=24 -SS-18 N=24 -SS-19 N=51 -SS-20 N=85 -SS-20 N=85 -SS-20 N=85 -SS-21 N=21 -SS-22 N=10 -SS-22 N=10 -SS-23 N=20 -SS-24 50/6"	_	ш∝	FT.	_	PIO (ppm)	907	455		,
Silty sand, poorly sorted, subrounded, gray and brown SS-14 N=16 SS-15 N=47 SS-16 N=28 CL Lean clay, gray, moist, trace sand SS-17 N=41 SS-18 N=24 SS-18 N=24 SS-18 N=24 SS-19 N=51 SS-20 N=85 CL Lean clay, gray, moist, some gravel Lean clay, gray, moist, some sand and gravel CL Lean clay, gray, moist, some sand and gravel CL Lean clay, gray, wet, subrounded Gravel, well graded, gray, wet, subrounded Gravel with sand, poorly sorted, gray, subrounded, wet SS-20 N=85 A0 SS-21 N=21 SS-22 N=10 SS-23 N=20 SS-24 50/6*	OEPTH feet	SAMPL	BLOWS/F	VALUES	PROFILE	GRAPHIC	20ור כרי	GEOLOGIC DESCRIPTION	REMARKS .
SS-14 N=16 SS-15 N=47 SS-16 N=28 CL Lean clay, gray, moist, trace sand SM Sity sand, tan, fine to coarse grained, subrounded to rounded, wet, some gravel Lean clay, gray, moist, some sand and gravel SS-18 N=24 SS-19 N=51 SS-20 N=85 40 Sity sand, tan, fine to coarse grained, subrounded to rounded, wet, some gravel Lean clay, gray, moist, some sand and gravel CL Lean clay, gray, wet, subrounded SS-20 N=85 CL Lean clay, gray, wet, subrounded Gravel with sand, poorty sorted, gray, subrounded, wet SS-21 N=21 SS-22 N=10 SM Sity sand, fine to coarse grained, gray, poorty sorted, subrounded, some gravel, wet		SS-13	N=15			1. 1	SM	Silty sand, poorly sorted, subrounded,	
SS-16 N=28 -SS-17 N=41 35—SS-18 N=24 -SS-19 N=51 -SS-20 N=85 40—SS-21 N=21 -SS-22 N=10 -SS-23 N=20 -SS-24 50/6* CL Lean clay, gray, moist, trace sand CL Lean clay, gray, moist, some gravel Lean clay, gray, moist, some sand and gravel GW Gravel, well graded, gray, wet, subrounded GW Gravel with sand, poorty sorted, gray, subrounded, wet SM Silty sand, fine to coarse grained, gray, poorty sorted, gray, poorty sorted, subrounded, some gravel, wet	-	SS-14	N=16			• •		gray and brown	
SS-17 N=41 -SS-18 N=24 -SS-18 N=24 -SS-19 N=51 -SS-20 N=85 -SS-21 N=21 -SS-21 N=21 -SS-22 N=10 -SS-23 N=20 -SS-24 50/6* -SS-24 50/6* -SS-24 50/6* -SS-24 50/6* -SS-24 50/6* -SS-3 N=20 -SS-24 50/6* -SS-24 50/6* -SS-3 N=20 -SS-24 50/6* -SS-24 50/6* -SS-3 N=20 -SS-24 50/6*		SS-15	N=47					***	-
SS-18 N=24 SS-18 N=24 SS-19 N=51 SS-20 N=85 40 SS-21 N=21 SS-22 N=10 SS-23 N=20 SS-24 50/6* SS-24 50/6* SS-24 S0/6* SS-24 S0/6* SS-25 SS-24 S0/6* SS-26 SS-2	-	SS-16	N=28				CL	Lean clay, gray, moist, trace sand	
SS-18 N=24 -SS-19 N=51 -SS-20 N=85 40 -SS-21 N=21 -SS-22 N=10 45-SS-23 N=20 -SS-24 50/6* CL Lean clay, gray, moist, some sand and gravel display. Gravel, well graded, gray, wet, subrounded gravel, well graded, gray, wet subrounded, gray, subrounded, wet SM Silty sand, fine to coarse grained, gray, poorly sorted, subrounded, some gravel, wet	-	SS-17	N=41			• •	SM	Silty sand, tan, fine to coarse grained, subrounded to rounded, wet, some gravel	-
SS-19 N=51 -SS-20 N=85 -SS-21 N=21 -SS-22 N=10 -SS-23 N=20 -SS-24 50/6* -SS-24 50/6* -SS-24 50/6* -SS-19 N=51 -SS-20 GW Gravel, well graded, gray, wet, subrounded -SG-20 GW Gravel, well graded, gray, wet, subrounded, gray, wet subrounded, wet -SG-20 GW Gravel, well graded, gray, wet, subrounded, gray, subrounded, wet -SG-21 N=21 -SG-22 N=10 -SG-24 50/6*	35_	55-18					CL	Lean clay, gray, moist, some sand and	
SS-20 N=85 W=85 W=85 W=85 W=85 W=85 W=85 W=10 SM Silty sand, fine to coarse grained, gray, poorly sorted, subrounded, some gravel, wet		33 10	N=24						
SS-20 N=85 40 SS-21 N=21 SS-22 N=10 SM Silty sand, fine to coarse grained, gray, poorly sorted, subrounded, wet SM Silty sand, fine to coarse grained, gray, poorly sorted, subrounded, some gravel, wet	-	SS-19	N=51						-
SS-21 N=21 -SS-22 N=10 -SS-23 N=20 -SS-24 50/6	-					000	GW	Gravel, well graded, gray, wet, subrounded	
SS-21 N=21 SS-22 N=10 SM Silty sand, fine to coarse grained, gray, poorly sorted, subrounded, wet SM Silty sand, fine to coarse grained, gray, poorly sorted, subrounded, some gravel, wet	1	SS-20	N=85			777		Lean clay, gray, wet	-
SS-22 N=10 O o SM Silty sand, fine to coarse grained, gray. poorly sorted, subrounded, some gravel, wet	l	SS-21	N=21			0 0		Gravel with sand, poorly sorted, gray, subrounded, wet	-
45—SS-23 N=20 —SS-24 50/6"		SS-22	N=10		·	0. 6	SM	Silty sand, fine to coarse grained, gray.	-
	45- -	SS-23	N=20					poorly sorted, subrounded, some gravel, wet	
-SS-25 N=59		SS-24	50/6'						-
Solution Terminated at 50.0 Feet	1	SS-25	N=59			• •			-
Boring Terminated at 50.0 Feet								Boring Terminated at 50.0 Feet	




EMCON

603 E. Diehl Road, #123 Naperville, Illinois 60563

LOG OF BORING MW-205 Page 1 of 2

	PRO	JECT	NAM	E:	Mallard North L	andfi	<i>'</i> //		DATE: December 28, 1998		
[PROJECT NUMBER: 795416								DEPTH TO WATER:		
ĺ	LOCATION: Hanover Park, Illinois								TOTAL DEPTH: 40.0 feet		
ĺ	LOGGED BY: Mike Barinek								DRILLER/METHOD: Fox / H	HSA	
			Т.		PID (ppm)	.06	SS				
	DEPTH feet	SAMPLE	BLOWS/FT.	VALUES	PROFILE	GRAPHIC LOG	SOIL CLASS	GE	OLOGIC DESCRIPTION	REMARKS	
		SS-1					ОН	Black organ gravel	ic topsoil, moist, roots, some		
		33-1	N=14				CL	Lean clay, n trce sand a	noist, mottled brown and gray, nd gravel]	
	4	SS-2	N=34						.*		
	5-	SS-3	N=58								
)		SS-4	N=54		·			gray _.			
	10-	SS-5	N=22		·			:			
	•	SS-6	N=20								
	-	SS-7	N=10								
	15-	SS-8	N=35							-	
	1	SS-9	N=15				GW CL-MI		graded, gray, subrounded, wet		
İ		SS-10	N=15					L-MI	Lean clay, i sand	gray, moist, some gravel, trace	-
	20-	SS-11	N=22								
P* -	-	SS-12	N=31								
	25-	SS-13	N=14							-	



LOG OF BORING MW-205 Page 2 of 2

P							i//	DATE: December 28, 1998	٦
Р	ROJE	ECT	NUMI	BER:	795416			DEPTH TO WATER:	
L	OCA	1017	√ : <i>⊦</i>	lano	ver Park, Illinoi:	s	·	TOTAL DEPTH: 40.0 feet	
L	OGG	ED E	3Y:	Mike	Barinek			DRILLER/METHOD: Fox / HSA	
 	u	4 E	ੌFΤ.	<u> </u>	PID (ppm)	907	CLASS		
ОЕРТН	fee	NUMBER	BLOWS/FT.	VALUES	, PROFILE	GRAPHIC LOG	SOIL	GEOLOGIC DESCRIPTION REMARKS	
	ss	5-13	N=14				CL-ML	Clayey silt, gray, wet, some sand, trace gravel	į
	-ss	6-14	N=14						
30		6-15	N=16	į				- "	
	- 1	6-16	N=16						
	-ss	6-17	N=11	l					
35	5ss	5-18	N=14						
	- 55	6-19	N=16						
	t	6-20	N=16						
40	-							Boring Terminated at 40.0 Feet	
	1								
4	5-		,						-
									1
	-								_
50	D-								-
L			<u> </u>		1	<u> </u>			

ILLINOIS ENVIRONMENTAL PROTECT	ION AGENCY	WE	LL COMF	PLETION R	EPORT
SITE # :0434485002	COUNTY: Dupage	····	WELL #:	MW-204S	
SITE NAME: Mallard North Landfill			BOREHOLE	#: B-204	
RDINATES: N -1178.04 E 961.33 (or)	LATITUDE	LONGIT	UDE		
SURVEYED BY:	ILL. REGISTRATI	on #:			
DRILLING CONTRACTOR: Fox Contractors	DRILLER: Don	Eger		·	
CONSULTING FIRM: EMCON	GEOLOGIST: _M	like Barnick			
DRILLING METHOD: HSA	DRILLING FLUIÇ	S (TYPE): None			
LOGGED BY: Mike Barnick		12/23/98 DA	ATE FINISHE	D: 12/23/98	3
REPORT FORM COMPLETED BY: STEPHEN HEUER	DATE: 4/19/9	9			
ANNULAR SPACE DETAILS	EL	EVATIONS DE (MSL)* (E	PTHS BGS)	(0.1 ft)	
		776.71		TOP OF PROTECTIVE	CASING
		776.41	0.04	TOP OF RISE	
TYPE OF SURFACE SEAL: CONCRETE T & OF ANNULAR SEALANT: BENTONITE CHIPS		774.4	0.00	GROUND SUP	RFACE
INSTALLATION METHOD: FREE DROP SETTING TIME:		771.4	3.00	TOP OF ANNULAR SE	ALANT
TYPE OF BENTONITE SEAL: GRANULAR PELLET CHIPS INSTALLATION METHOD: SETTING TIME:	\ \\	753.51 2	20.89	WATER LEVEL (AFTER COMPLETION DATE: 2/18/99	
TYPE OF SAND PACK: #5 Filter Sand				TOP OF SEA	L
GRAIN SIZE: (SIEVE SIZE) INSTALLATION METHOD: FREE DROP		761.4	13	TOP OF SAN	DPACK
TYPE OF BACKFILL MATERIAL: (IF APPLICABLE) INSTALLATION METHOD:		756.46 1	7.94	TOP OF SCR	EEN
, more buildings.		741.96 3	32.94	BOTTOM OF	SCREEN
		741.71	32.69	BOTTOM OF	WELL
		741.40	33	BOTTOM OF	
·		* REFERENCED TO /	A NATIONAL GEOD	_	M.
WELL CONSTRUCTION MATERIALS (ORCLE ONE)		CASING N	IEASUREMEN	ITS	
\		TER OF BOREHOLE		(in)	8 2.0

DIAMETER OF BOREHOLE	(in)	8
ID OF RISER PIPE	(in)	2.0
PROTECTIVE CASING LENGTH	(ft)	5.0
RISER PIPE LENGTH	(ft)	19.45
BOTTOM OF SCREEN TO END CAP	(ft)	.25
SCREEN LENGTH (1st SLOT TO LAST SLOT)	(ft)	15
TOTAL LENGTH OF CASING	(ft)	34.7
SCREEN SLOT SIZE **	(in)	0.01

** HAND-SLOTTED WELL SCREENS ARE UNACCEPTABLE

(\$3304)

\$\$315

SS315

PTPE

PTPE

PTPE

OTHER:

OTHER:

RISER PIPE ABOVE W.T.

RISER PIPE BELOW W.T.

REMARKS:

A HANGE SANGERS OF THE STATE OF THE SANGERS OF THE	DENOV
ILLINOIS ENVIRONMENTAL PROTECTION A	GENCY WELL COMPLETION REPORT
SITE #: 0434485002 COUN	TY: Dupage WELL #: MW-204D
STE NAME: Mallard North Landfill	BOREHOLE #: B-204
OURDINATES: N -118.36 E 956.11 (or) LATITUL	ELONGITUDE
SURVEYED BY:	ILL. REGISTRATION #:
DRILLING CONTRACTOR: Fox Contractors	DRILLER: Don Eger
CONSULTING FIRM: EMCON	GEOLOGIST: Mike Barnick
DRILLING METHOD: HSA	DRILLING FLUIDS (TYPE): None
LOGGED BY: Mike Barnick	DATE STARTED: 12/22/98 DATE FINISHED: 12/22/98
REPORT FORM COMPLETED BY: STEPHEN HEUER	DATE: 4/19/99
	·
ANNULAR SPACE DETAILS	ELEVATIONS DEPTHS (0.1 ft) (MSL)* (BGS)
	777.53 —3.13 TOP OF PROTECTIVE CASING
	777.23 —2.83 TOP OF RISER PIPE
TYPE OF SURFACE SEAL: CONCRETE OF ANNULAR SEALANT: Cement—Bentonite Grout	774.4 0.00 GROUND SURFACE
INSTALLATION METHOD: TREMIE PIPE SETTING TIME:	771.4 3.00 TOP OF ANNULAR SEALANT
TYPE OF BENTONITE SEAL: GRANULAR PELLED INSTALLATION METHOD: FREE DROP SETTING TIME:	751.06 23.34 WATER LEVEL (AFTER COMPLETION) DATE: 2/18/99.
TYPE OF SAND PACK: #5 Filter Sand	740.4 34 TOP OF SEAL
GRAIN SIZE:(SIEVE SIZE) INSTALLATION METHOD: FREE DROP	
TYPE OF BACKFILL MATERIAL: (# APPLICABLE)	734.18 40.22 TOP OF SCREEN
INSTALLATION METHOD:	724.18 <u>50.22</u> BOTTOM OF SCREEN
	723.93 50.47 BOTTOM OF WELL
	723.4 51 BOTTOM OF BOREHOLE
WELL CONSTRUCTION	* REFERENCED TO A NATIONAL GEODETIC VERTICAL DATUM
MATERIALS (CIRCLE ONE)	CASING MEASUREMENTS

PROTECTIVE CASING	SS304	SS315	PTPE	PVC	OTHER: STEEL
RISER PIPE ABOVE W.T.	\$5304)	SS315	PTPE	PVC	OTHER:
PISER PIPE BELOW W.T.	(5304)	SS315	PTPE	PVC	OTHER:
EN	(\$330)	SS315	PTPE	PVC	OTHER:


	62270	33313	PIPE	PVC	UIREN.	
REMARKS:	 					
	 					

DIAMETER OF BOREHOLE	(in)	8
ID OF RISER PIPE	(in)	2.0
PROTECTIVE CASING LENGTH	(ft)	5.0
RISER PIPE LENGTH	(ft)	43.05
BOTTOM OF SCREEN TO END CAP	(ft)	.25
SCREEN LENGTH (1st SLOT TO LAST SLOT)	(ft)	10
TOTAL LENGTH OF CASING	(ft)	53.3
SCREEN SLOT SIZE **	(in)	0.01

** HAND-SLUTTED WELL SCREENS ARE UNACCEPTABLE

ILLINOIS ENVIRONMENTAL PROTECTION A	GENCY WELL COMPLETION REPORT
SITE #: 0434485002 COUR	NTY: Dupage WELL #: MW-205
	BOREHOLE #: B-205
ADINATES: N -1000.63 E 1266.85 (or) LATITUE	
	ILL. REGISTRATION #:
	DRILLER: Don Eger
CONSULTING FIRM: EMCON	:
DRILLING METHOD: HSA	
	DATE STARTED: 12/28/98 DATE FINISHED: 12/28/98
REPORT FORM COMPLETED BY: STEPHEN HEUER	
ANNULAR SPACE DETAILS	ELEVATIONS DEPTHS (0.1 ft) (MSL)* (BGS)
• •	786.10 —2.5 TOP OF PROTECTIVE CASING
	785.80 —2.2 TOP OF RISER PIPE
YPE OF SURFACE SEAL: CONCRETE -	783.6 0.00 GROUND SURFACE
OF ANNULAR SEALANT: BENTONITE CHIPS INSTALLATION METHOD: FREE DROP SETTING TIME:	
TYPE OF BENTONITE SEAL: GRANULAR PELLET CHIPS INSTALLATION METHOD: TOTAL CHIPS OF BENTONITE SEAL: GRANULAR PELLET CHIPS OF BENTONITE SEAL: 761.46 22.14 WATER LEVEL (AFTER COMPLETION) DATE: 2/18/99	
YPE OF SAND PACK: #5 Filter Sand	TOP OF SEAL
GRAIN SIZE: (SIEVE SIZE) INSTALLATION METHOD: FREE DROP	
YPE OF BACKFILL MATERIAL: (IF APPLICABLE)	757.85 25.75 TOP OF SCREEN
INSTALLATION METHOD:	742.85 40.75 BOTTOM OF SCREEN
	742.85 40.75 BOTTOM OF SCREEN 742.90 40.7 BOTTOM OF WELL
	740.00
(iv. • = i	# REFERENCED TO A NATIONAL GEODETIC VERTICAL DATUM
WELL CONSTRUCTION	
MATERIALS (ORCLE ONE)	CASING MEASUREMENTS DIAMETER OF BOREHOLE (in) 8
* ROTECTIVE CASING SS304 SS315 PTPE PVC OTHER: STE	······································
SER PIPE ABOVE W.T. \$300 SS315 PTPE PVC OTHER:	PROTECTIVE CASING LENGTH (ft) 5.0
SFR PIPE BELOW W.T. \$300 SS315 PTPE PVC OTHER:	RISER PIPE LENGTH (ft) 27.65
N SS304 SS315 PTPE PVC OTHER:	BOTTOM OF SCREEN TO END CAP (ft) .25
, THADICO	SCREEN LENGTH (1st SLOT TO LAST SLOT) (ft) 15
/ TMARKS:	TOTAL LENGTH OF CASING (ft) 42.9
	SCREEN SLOT SIZE *** (in) 0.01
	## HAMD_SITTED WELL SOPERING ARE INJUNCEDING

4/85057050\000\NAMNWCTP.DWG 4/21/99




· - - - - - - - -1 Attachment 2

Well G54S
Well Construction Information



Illinois Environmental Protection Agency - Well Completion Report



MEASUREMENTS

WELL CONSTRUCTION MATERIALS (CIRCLE ONE)

<u></u>	
PROTECTIVE CASING	SS304, SS316, PTFE, PVC OR THER AI
RISER PIPE ABOVE W.T.	SS304, SS316, PTFE, PVO OR OTHER:
RISER PIPE BELOW W.T.	SS304, SS316, PTFE PV OR OTHER:
SCREEN	SS304, SS316, PTFE PVC OR OTHER:

DIAMETER OF BOREHOLE (in)	6
ID OF RISER PIPE (in)	2
PROTECTIVE CASING LENGTH (ft)	7
RISER PIPE LENGTH (ft)	46.1
BOTTOM OF SCREEN TO END CAP (ft)	0.08
SCREEN LENGTH (1st slot to last slot)	5'
TOTAL LENGTH OF CASING (ft)	51.1
SCREEN SLOT SIZE **	0.01"

[&]quot; HAND-SLOTTED WELL SCREENS ARE UNACCEPTABLE

Mallard Lake Landfill Monitoring Well As Built Diagram G-154

Elevation above Mean Sea Level Top of PVC Casing: 785.38 Top of PVC Casing: 785.38 Top of PVC Casing: 3.1' Northing: 4369 Easting: 1024 Ground Surface: 782.28 Ground Surface: 782.28 Ground Surface: 0.0' Type of Surface Seal: Concrete Top of annular seal: 778.28 Top of annular seal: 4.0' **Bottom of Protective** Bottom of Protective Casing: 3.9' Casing: 778.38 Type of Annular Seal: Aquaguard Bentonite Grout for Groundwater Monitoring Riser Material: Schedule 40 PVC from 47' to 2.5' Centralizer (s): yes/no Riser Diameter: 2 inches Top of Secondary Sand: Top of Secondary Sand: 36' 746.28 Type of Primary Seal: Same as Annular Seal Top of Sand Pack: 744.28 Top of Sand Pack: 38' Type of Secondary Sand Pack: R.W. Top of Screen: 740.28 Top of Screen: 42' Sidley 100 grade Sand Type of Primary Sand Pack: R.W. Sidley 10/20 Coarse Sand Screen Slot Size: Campbell Monoflex Screens 10 Slot Type Bottom of Screen: 735.28 Bottom of Screen: 47' Total Depth : <u>734.28</u> Total Depth: 48'

Herst & Associates, Inc.

1	
I.	
I	
' 	, ,
, 	
	r 1
	r 3
I	
	. ,
•	
· I	
	<i>r</i> 7
I	, <u>,</u>
ı	
	, ,
	, ,
	•
	, ,
	•
	L 4
	, ,
	, ,
	. ,
	. 4
	, ,
	` 1
	. ,
	, ,
	` ′
	, ,
	. ,
	,
	, ,
	, ,
	, ,
	, ,
	, ,
	, , , , , , , , , , , , , , , , , , ,
	, , , , , , , , , , , , , , , , , , ,

WELL CONSTRUCTION REPORT

TYPE OR PRESS FIRMLY WITH BLACK INK PEN, THIS FORM MUST BE COMPLETED WITHIN 30 DAYS OF COMPLETION AND SENT TO THE APPROPRIATE HEALTH DEPARTMENT

1. Date Well Completed September 13, 20	000	<u></u>	
2. Use: [] Domestic [] Irrigation [] Con		vestock	
[X] Monitoring [] Other			
3. Type of Well:			
a. Bored Well: Hole Diameter	in. Depth_		<u>n.</u>
Casing Diameter in. Buried			
b. Driven Well: Drive Pipe Diameter_			ft.
c. Drilled Well: Well Diameter 6	in. Depth	<u>48</u> n	
Casing Diameter 2 in. Type	PVC	Joint trl	hreaded
	Oversized		
Kind		From(ft)	<u>To(fi)</u>
R.W. Sidley 1020 Sand	6	47	38
R.W. sidley 100 Grade Sand	0	38	36
Aauaguard Bentonite Grout	6	36	0
Finished In: Unconsolidated [X] Gra	vel Pack: []Y	cs []No	
Rock [] Grain Size_	1.00		
4. Well Disinfected? []Yes []No			
5. Date Permanent Pump Installed			·-
6. Licensed Pump Contractor	·····		
License Number		·····	
7. Pitless Adapter Installed? []Yes []No	•		
Manufacturer	Mo	odel	
Attached to Casing - How? [] Screwed	On [] Welde	d [] Com	ipression
8. Type of Well Cap			
9. Tank Working Cyclogallon	is Captive Air	:[]Yes [JNo
10. Pump and Equipment Disinfected? []Yes []No		
General Comments: (If dry hole, fill out lo	g & indicate ho	w hole wa	is scaled.)
Illinois Department of Public Health Division of Environmental Health - 525 W Springfield, IL 62761	. Jefferson		
IMPORTANT NOTICE. This Sode Agency is requesting dis-	chieure of information	ital je nocesse	ny to accomplish

the statutory purpose se certified under Public Act 85-0865. Disclosure of this information is manufactury. This

form has been approved by the Forms Management Center.


GEOLOGICAL AND WATER SURVEY WELL RECORD


11. Permit Number	Date Issuo	d
12. Property Owner Forest Preserve District of		
13. Drilling Company Name Layne North	iwest	
14. Name of Person who drilled the well		
15. Well Site Address 26W580 Schick Roa	d	
16. Twishp Name	L	and ID#
		f
18. Location: Cnty Du Page Sect	18 Twnshp T4	ON Range RIOE
NW Quarter of the NW Qua	nter of the NW	_Quarter
19. Casing and Liner Pipe:		20. Screen:
Dia (In) Type	From(ft) To (ft)	Diameter 2 in.
2 Schedule 40 PVC	47 0	Length 5 ft.
		Slot Size 0.01"
		Material PVC
21 Water from	at depth	
22. Static Level 5.7 ft, below casing top	which is 30	in, above ground level.
Pumping Level ft. Pumping	gpm for	hours.
23. Earth Materials Passed Through		Depth Bottom(ft)
gray clay	0	10
gray to brown silty clay	10	15
seal wall	15	18
gray to brown silty clay	18	44
fine to coarse gravel	44	48
Continue of Aack of shoet Maccessury		
111 Walle		102-003431

Licensed Contractor Signature

License Number

Figure 4
Mallard Lake Landfill
W1/W2 Groundwater Elevations (msl)





Attachment 3

Previous Investigation Boring Logs and Well Details

	C	3			1	CLIENT BFI Waste Systems of	North America, Inc.	LOG OF	BORING NUM	BER	ML-	-6I		
			۱۱		F	PROJECT NAME		ARCHITE	CT-ENGINEE	R	-			
	STS Cor	sulta	nts L	d.		Mallard Lake Landfill			1	- UNCC	NENE	D COUR	ESSIVE	STRENGTH
	Han			arl	κ, Ι	L				TONS	/FT. ²	3	4	5
	T) ON(FT)		111	ANCE		DECOS	DIDTION OF MATERIAL			PLASTIC		WATER		LIQUID LIMIT %
	DEPTH(FT) ELEVATION(FT)	SAMPLE NO.	SAMPLE TYPE	LE DIST	VERY	DESCR	RIPTION OF MATERIAL		UNIT DRY WT.	10	20	30 TANDARD	40	50
ŀ	<u> </u>	SAME	SAME	SAME	RECC	SURFACE ELEVATION			UNIT	⊗ 10		ENETRATI		DWS/(FT) 50
ľ				T	Т	Silty clay - trace gravel - t	prown - stiff (CL)				T	Ĭ	Ť	T
		1	GP		Ц									
	5.0	2	GP											
	10.0	3	GP											
	15.0	4	GP											
ŀ	19.7			1		Silty clay - trace gravel, so Note: thin lense sandy s	and - gray - stiff - moist (CL)						1	
	20.0	5	GP			Note. unit lense salidy s	iii 20.1 - 20.2							
		6	GP											
	25.0	7	GP				DRAFT							
	30.0	8	GP											
	35.0	9	GP				·							
	40.0	10	GP											
,/u8	44.0	11	GP			CH ₄ = 0.4%								
213.601 9/1/						End of boring								
15.GPJ 51														
10481		The	stra	ific	ati	on lines represent the appro	oximate boundary lines betwe	en soil typ	es: in situ,	the trans	ition r	may be	gradua	al.
3	WL						BORING STARTED 9/2/08		STS OFFICE	(Chica	go - 01		
ادّ او	WL						BORING COMPLETED 9/3/08		ENTERED BY PME	3	SHEE		OF	1
	WL						RIG/FOREMAN /		APP'D BY	2	STS J	0B NO. 200	70480	 5

Illinois Environmental Protection	Agency	•	Well Comp	pletion Report
Site Number: 0438010004	County: _I	DuPage		
Site Name: Mallard Land Landfill #2				Well #: ML-61
State Plane Coordinate: X Y (or) Latitude:	o ' " Long	o gitude:		Borehole #: ML-61
Surveyed by:				
Drilling Contractor: Terra Trace Environmental		Driller: Dennis		
Consulting Firm: STS		Geologist: Cra	aig Rawlins	on
Drilling Method: Geoprobe		Drilling Fluid ((Type): <u>N/A</u>	
Logged By: Matt Weiss		Date Started: 9	2/2/08	Date Finished: 9/3/08
Report Form Completed By: Matt Weiss		Date: 9/17/08	·	
ANNULAR SPACE DETAILS	SV.	Elevations (MSL)*	Depths (BGS)	(.01ft.) Top of Protective Casing
			0.5	Top of Riser Pipe
Type of Surface Seal: Granular Bentonite				Ground Surface
Type of Annular Sealant: Granular Bentonite			1.0	Top of Annular Sealant
Installation Method: Gravity			39.85	Static Water Level (After Completion)
Setting Time: 24 hours Type of Bentonite Seal Graffular, Pellet, Slurry (Choose One)			1.0	Top of Seal
Installation Method: Gravity			22	Top of Sand Pack
Setting Time: 24 hours			23.3	Top of Screen
Type of Sand Pack: Coarse Silica Sand			42.5	Bottom of Screen
Grain Size: No. 5 (Sieve Size)			42.7	Bottom of Well
Installation Method: Gravity	<u> </u>		44	Bottom of Borehole
Type of Backfill Material: In-situ Clay		* Referenced	to a National G	

(if applicable)

Installation Method: Cave-in

WELL CONSTRUCTION MATERIAL

(Choose one type of material for each area)

Protective Casing	SS304, SS316, PTFE, PVC, or Offer
Riser Pipe Above W.T.	SS304, SS316, PTFE, PVC, or Other
Riser Pipe Below W.T.	SS304, SS316, PTFE, PVC, or Other
Screen	SS304, SS316, PTFE, PVC, or Other

CASING MEASURMENTS

Diameter of Borehole (inches)	2.0
ID of Riser Pipe (inches)	0.75
Protective Casing Length (feet)	1.0
Riser Pipe Length (feet)	5.0
Bottom of Screen to End Cap (feet)	0 2
Screen Length (1st slot to last slot) (feet)	19.2
Total Length of Casing (feet)	23 3
Screen Slot Size **	0.010

^{**}Hand-Slotted Well Screens are Unacceptable

		Ī			LIENT	LOG OF	BORING NU	MBER	ML-6S			
	7				3FI Waste Systems of North America, Inc.							. ,
	_				ROJECT NAME Mallard Lake Landfill	ARCHITE	CT-ENGINE	ER				
STS Cor			d.		Valiaiu Lake Laiiuiii			-O-UNG	CONFINED CO	MPRESSIN	/E STREI	NGTH
Har			arl	ς, Ι	L			TON	CONFINED CO NS/FT. ² 2	3 4	5	
								PLAST	ric wa	TER	LIQU	110
) (FT			NO					LIMIT	% CONT	ENT %	LIMIT	-%
DEPTH(FT) ELEVATION(FT)	è	TYPE	DIST/	≿	DESCRIPTION OF MATERIAL		WT	10	20	30 40	<u>-</u> ∆ □ 50	
DEPTH(FT) ELEVATION	SAMPLE NO.	SAMPLE TYPE	PLE	OVE			. DRY		STANDA	+		
M	SAM	SAM	SAM	RECOVERY	SURFACE ELEVATION		UNIT DRY WT.	⊗ 10	PENETF 20 3	RATION B	LOWS/(F	T) .
			П		Blind drill to 20 ft							
	1			ļ			İ					
	1											
5.0]	
											İ	
			$\ \ $	- {			}	}				
10.0	1	GP	П		_	-					ŀ	
	'	GF			- AE		ļ					
	}		i	İ	DRAF	•						
15.0	}			1								
											l	
				1								i
20.0			Ц									
			Į		End of boring							. 1
				•								
				-							ĺ	
1												
,			- {	-								
1												1
ĺ		ĺ	İ				ļ.		+			
		Ì	}									
	,											
1												
							ĺ					
8												
807.1												
00.010												
2												
§	The	ctro	ific	اب	on lines represent the approximate boundary lines betw	man soil to	es: in site:	the tra-	eition may	he grad	<u></u>	
				all		cen son typ	_===				Jai.	
∛ WL 3					BORING STARTED 9/3/08		STS OFFICE		Chicago - 0			
WL.					BORING COMPLETED 9/3/08		ENTERED B	B	SHEET NO	1 OF	1	
WL					RIG/FOREMAN /	_	APP'D BY		STS JOB NO). 2007048	05	

Illinois Environmental Protection Agency

Well Completion Report

Site Number: 0438010004	County: DuPage	
Site Name: Mallard Lake Landfill #2		Well #: ML-6S
State o Plane Coordinate: X Y (or) Latitude:	O " Longitude:	Borehole #: ML-6S
Surveyed by:	IL Registration #:	
Drilling Contractor: Terra Trace Environmental	Driller: Dennis	
Consulting Firm: STS	Geologist: Craig Rawlinso	on
Drilling Method: Geoprobe	Drilling Fluid (Type): N/A	
Logged By: Matt Weiss	Date Started: 9/3/08	Date Finished: 9/3/08
Report Form Completed By: Matt Weiss	Date: 9/17/08	

Elevations ANNULAR SPACE DETAILS **Depths** (.01ft.)(MSL)* (BGS) Top of Protective Casing 0.5 Top of Riser Pipe Type of Surface Seal: Granular Bentonite Ground Surface 1.0 Type of Annular Sealant: Granular Bentonite Top of Annular Sealant Installation Method: Gravity Static Water Level (After Completion) Setting Time: 24 hours Type of Bentonite Seal - - Graffular, Pellet, Slurry 1.0 Top of Seal (Choose One) Installation Method: _Gravity Top of Sand Pack 5.2 Setting Time: 24 hours Top of Screen Type of Sand Pack: Coarse Silica Sand 15 Bottom of Screen 15.2 Grain Size: No. 5 (Sieve Size) Bottom of Well Installation Method: _ Gravity 20 Bottom of Borehole * Referenced to a National Geodetic Datum Coarse Silica Sand Type of Backfill Material: (if applicable) CASING MEASURMENTS Installation Method: Gravity

WELL CONSTRUCTION MATERIAL (Choose one type of material for each area)

Protective Casing	SS304, SS316, PTFE, PVC, or Other
Riser Pipe Above W.T.	SS304, SS316, PTFE, PVC, or Other
Riser Pipe Below W.T.	SS304, SS316, PTFE, PVC, or Other
Screen	SS304, SS316, PTFE, PVC, or Other

	T
Diameter of Borehole (inches)	2.0
ID of Riser Pipe (inches)	0,75
Protective Casing Length (feet)	0.8
Riser Pipe Length (feet)	5.0
Bottom of Screen to End Cap (feet)	0.2
Screen Length (1st slot to last slot) (feet)	9.8
Total Length of Casing (feet)	5.0
Screen Slot Size **	0.010

^{**}Hand-Slotted Well Screens are Unacceptable

CLIENT LOG OF BORING NUMBER GPT-7 BFI Waste Systems of North America, Inc. PROJECT NAME ARCHITECT-ENGINEER Mallard Lake Landfill O UNCONFINED COMPRESSIVE STRENGTH TONS/FT.²
1 2 3 4 5 SITE LOCATION Hanover Park, IL LIQUID **PLASTIC** WATER ELEVATION(FT) SAMPLE DISTANCE CONTENT % LIMIT % DEPTH(FT) UNIT DRY WT. LBS./FT.3 \times **DESCRIPTION OF MATERIAL** 10 30 50 STANDARD PENETRATION BLOWS/(FT) SURFACE ELEVATION Silty clay - trace gravel - brown - stiff - (CL) 1 GP 5.0 2 GP 10.0 Silty fine to coarse sand - trace gravel - brown-gray - moist to wet 3 GP (SM) 4 GP 15.0 Clayey silt - trace gravel, sand - gray (ML) 5 GP 20.0 DRAFT End of boring STS.GDT 200704805 The stratification lines represent the approximate boundary lines between soil types: in situ, the transition may be gradual. WL BORING STARTED STS OFFICE Chicago - 01 9/2/08 WL BORING COMPLETED 9/2/08 ENTERED BY PMB SHEET NO. APP'D BY
CSR STS JOB NO. 200704805 WL RIG/FOREMAN



Report Form

Completed By: Matt Weiss

Illinois Environmental Protection Agency

Well Completion Report

Site Number: 0438010004 County: DuPage Well #: GPT-7 Site Name: Mallard Lake Landfill #2 State Borehole #: GPT-7 Plane Coordinate: X ____ Y ___ (or) Latitude: ___ Longitude: Surveyed by: IL Registration #: Drilling Contractor: Terra Trace Environmental Driller: Dennis Geologist: Craig Rawlinson Consulting Firm: STS Drilling Method: _Geoprobe Drilling Fluid (Type): N/A Logged By: _Matt Weiss Date Started: 9/2/08 Date Finished: 9/2/08

Type of Surface Seal: Granular Bentonite Type of Annular Sealant: Granular Bentonite Installation Method: Gravity Setting Time: 24 hours Type of Bentonite Seal - - Graxular, Pellet, Slurry (Choose One) Installation Method: Gravity Setting Time: 24 hours Type of Sand Pack: Coarse Silica Sand Grain Size: No. 5 (Sieve Size) Installation Method: Gravity

levations ISL)*	Depths (BGS)	(.01ft.)		
	0	Top of Protective Casing		
	0.5	Top of Riser Pipe		
	0	Ground Surface		
	1.0	Top of Annular Sealant		
	dry to 12.78	Static Water Level (After Completion)		
	1.0	Top of Seal		
	3.5	Top of Sand Pack		
	3.5	Top of Screen		
	13.5	Bottom of Screen		
	13.7	Bottom of Well		
+ 5 6	20	Bottom of Borehole		

* Referenced to a National Geodetic Datum

CASING MEASURMENTS

Date: 9/17/08

	T
Diameter of Borehole (inches)	2.0
ID of Riser Pipe (inches)	0.75
Protective Casing Length (feet)	0.8
Riser Pipe Length (feet)	5.0
Bottom of Screen to End Cap (feet)	0.2
Screen Length (1st slot to last slot) (feet)	9.8
Total Length of Casing (feet)	3.7
Screen Slot Size **	0,010

^{**}Hand-Slotted Well Screens are Unacceptable

Type of Backfill Material: In-situ Sand

Installation Method: Blow-in
WELL CONSTRUCTION MATERIAL

(if applicable)

(Choose one type of material for each area)

SS304, SS316, PTFE, PVC, or Other

SS304, SS316, PTFE, PVC, or Other

SS304, SS316, PTFE, PVC, or Other

Protective Casing

Riser Pipe Above W.T

Riser Pipe Below W.T.

	BFI Waste Systems of North America, Inc.	LOG OF BORING NO	MBEK	GPT-8	
	PROJECT NAME	ARCHITECT-ENGINE	ER		
STS Consultants Ltd.	Mallard Lake Landfill			_	
SITE LOCATION			-O-UNC	ONFINED COMP	PRESSIVE STRENGTH
Hanover Park	, IL			2 3	4 5
DEPTH(FT) ELEVATION(FT) SAMPLE NO. SAMPLE TYPE SAMPLE DISTANCE	DESCRIPTION OF MATERIAL		PLASTI LIMIT 9		
DEPTH(FT) ELEVATION IPLE NO. IPLE DISTAI	DESCRIPTION OF MATERIAL	, w⊤	10	20 30	40 50
DEPTH(FT ELEVATIO) SAMPLE NO. SAMPLE TYPE SAMPLE DISTA		UNIT DRY WT.		STANDAR	
S S S S	SURFACE ELEVATION	N 2	10	20 30	TION BLOWS/(FT) 40 50
	Silty clay - brown - medium - moist (CL)	ļ		, ,	
1 GP		j		1 1	
5.0	$oldsymbol{H}$				
2 GP	CH ₄ = 0.6%		1 1		
2 6 1					1 1
			 		
10.0 3 GP	Silty fine to coarse sand - gray - wet (SM) CH ₄ = 0.2%				
	Clavey silt - trace sand - gray - medium - moist (ML)		+		
	Note: suspected blow-in from upper silty sand encour 16-20 ft sample	ntered in			
15.0 4 GP	10-20 it Sample	ļ			
	r				
5 GP		1			
20.0		-			
			11-		
	End of boring				
	DRAFT				
	DKAI .				
		j			
1			1		
1170					
6 10					
13.6					
2					
0.5.G					
The stratification lines represent the approximate boundary lines between soil types: in situ, the transition may be gradual.					
% WL	BORING STARTED 9/2/08	STS OFFIC	<u> </u>	Chicago - 01	
9 wr	BORING COMPLETED	ENTERED		SHEET NO	OF
CONTING LOG 200704805 GPJ 3175 GDT 9/17/08 The stratification of the stratification of	9/2/08 RIG/FOREMAN	APP'D BY	18	STS JOB NO.	1
<u> </u>	I NOT OTENAT	C:	R	20	0704805



Illinois Environmental Protection Agency

Well Completion Report

Site Number: <u>043801</u>0004 County: _DuPage

Site Name: Mallard Lake Landfill #2		Well #: GPT-8
State Plane Coordinate: X Y (or) Latitude:	o ' " o ' " Longitude:	Borehole #: GPT-8
Surveyed by:	IL Registration #:	
Drilling Contractor: Terra Trace Environmental	Driller: Dennis	
Consulting Firm: STS	Geologist: Craig Rawlins	on
Drilling Method: Geoprobe	Drilling Fluid (Type): N/A	
Logged By: Matt Weiss	Date Started: 9/2/08	Date Finished: 9/2/08
Report Form Completed By: Matt Weiss	Date: 9/17/08	

ANNULAR SPACE DETAILS	DRAF MSL)*	Depths (BGS)	(.01ft.)
	DRAFI	0	Top of Protective Casing
		0.5	Top of Riser Pipe
Type of Surface Seal: Granular Bentonite		0	Ground Surface
Type of Annular Sealant: Granular Bentonite		1.0	Top of Annular Sealant
Installation Method: Gravity		4.60	Static Water Level (After Completion)
Setting Time: 24 hours			(mer completion)
Type of Bentonite Seal Gra X ular, Pellet, Slurry (Choose Onc)		1.0	Top of Seal
Installation Method: Gravity		3	Top of Sand Pack
Setting Time: 24 hours		4.3	Top of Screen
Type of Sand Pack: Coarse Silica Sand		14.3	Bottom of Screen
Grain Size: No. 5 (Sieve Size)		14.5	Bottom of Well
Installation Method: Gravity		20	Bottom of Borehole
Type of Backfill Material: In-situ Sand	* Reference	d to a National Ge	odetic Datum

(if applicable)

Installation Method: Blow-in

WELL CONSTRUCTION MATERIAL

(Choose one type of material for each area)

Protective Casing	SS304, SS316, PTFE, PVC, or Other
Riser Pipe Above W.T.	SS304, SS316, PTFE, PWC, or Other
Riser Pipe Below W.T.	SS304, SS316, PTFE, PVC, or Other
Screen	SS304, SS316, PTFE, PVC, or Other

CASING MEASURMENTS

Diameter of Borehole (inches)	2.0
ID of Riser Pipe (inches)	0.75
Protective Casing Length (feet)	0.8
Riser Pipe Length (feet)	5.0
Bottom of Screen to End Cap (feet)	0 2
Screen Length (1st slot to last slot) (feet)	9.8
Total Length of Casing (feet)	4.5
Screen Slot Size **	0010

^{**}Hand-Slotted Well Screens are Unacceptable



"Drew Bergenthal" <dbergenthal@dupageforest. com>

10/23/2008 03:39 PM

Τo

Subject RE: Mallard Lake

Walter:

Attached is a drawing covering the entire Mallard North Landfill. I would suggest that we use DV-13 or SV-12 to get a gas sample. We do not know what G-119 well cluster is sampling and should be abandoned. The well clusters G-204 and G-205 across the river from G-119 were installed to replace G-119. I believe G-119 has not been sampled since approximately early 2000.

Thank you,

Drew Bergenthal Environmental Compliance Manager Forest Preserve District DuPage County 630-462-5655 office

----Original Message----

From: Nied.Walter@epamail.epa.gov [mailto:Nied.Walter@epamail.epa.gov]

Sent: Thursday, October 23, 2008 11:35 AM

To: Drew Bergenthal

Cc: Faryan.Steven@epamail.epa.gov

Subject: Re: Mallard Lake

Drew Thank you for this drawing. Do you have a drawing of the entire landfill? Have any of the monitoring wells been screened for CH4? Also, Can the G-119 well cluster be accessed to screen for CH4? Do you analytical results for Groundwater Samples from any of these Monitoring wells? Wally

"Drew Bergenthal" <dbergenthal@dup ageforest.com>

10/23/2008 10:20 AM STEVEN FARYAN/R5/USEPA/US@EPA,
Donna Twickler/R5/USEPA/US@EPA,
WALTER NIED/R5/USEPA/US@EPA,
<john.richardson@epa.state.il.us>
, "Rawlinson, Craig"
<Craig.Rawlinson@aecom.com>

CC

To

Steve:

Attached is a drawing for Mallard North. Let me know if this works, otherwise I can do more searching. Also, I do not have an email address for Om.

Thank you,

Drew Bergenthal Environmental Compliance Manager Office of Environmental Services Forest Preserve District of DuPage County (630) 462-5655

Save a tree. Please consider the environment before printing this e-mail.

CONFIDENTIALITY NOTICE: This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential, privileged or other information, protected by law. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, please contact the sender by reply e-mail and destroy all copies of the original message.

(See attached file: MN LCS.pdf)

<u>...</u>

Mallard North.pdf

Mallard Lake Landfill Status and Transition to IEPA Permits Update

- The sub-surface fire in the southeast corner of the site seems to be extinguished and the waste mass temperatures have fallen slowly and stabilized. A new subsurface fire was identified on the east side of the landfill near the waste perimeter. A number of gas extraction wells near the new fire have been closed (no vacuum applied), in order to reduce oxygen intrusion and suffocate the new fire.
- Recent perimeter gas monitoring data (August) indicates that there are two new locations where methane
 levels are exceeding the regulatory standard 50% or the LEL (25,000 ppm). One location is just east of
 the newly identified landfill fire. The other location is just north of the originally identified subsurface
 methane gas plume located under the neighborhood (west of the site), which will slightly expand the
 characterized plume.
- USEPA is reviewing the Responsible Party (RP) proposed approach to further characterize the subsurface methane contamination detected in August northeast of the site (at ML-6), near an elementary school. (The school has been tested and found to be free of methane. An explosimeter has been installed in the school to provide early warning of methane release.)
- USEPA presented the corrective action plan (CAP) to the community at public meetings on Oct 1. The CAP involves: 1) improvement to the on-site gas collection and management system, the landfill cover and the perimeter gas monitoring and 2) installation of extraction wells in the neighborhood west of the site to remove methane to 50% of the LEL (25,000 ppm), and as low as 5% of the LEL if possible, and treat the methane using multiple mobile combustion units. Due to concerns expressed by the public, USEPA intends to make the enhanced perimeter monitoring data available to the public via the Mallard Lake website.

Background

- USEPA intends to continue operating under the Administrative Order on Consent (AOC) for Mallard Lake until 1) the CAP clean-up levels (50% of LEL) are achieved; and 2) an enhanced monitoring system on the west perimeter of facility indicates for a year that methane levels not exceeding 50% of the LEL. Much of the CAP construction and implementation are underway. Seven new gas extraction wells (Phase 1) will be installed west of the landfill in the residential neighborhood and forest preserve, and extracted methane will be destroyed in mobile combustion units. After 5-6 months of extraction, data will be evaluated to determine whether clean-up levels have been achieved under the off-site neighborhood. Concurrently, the nature and extent of contamination investigation on the northeast side of the landfill will continue, in order to determine whether the landfill is the source of this contamination and the enhanced monitoring network on the west side of the facility will be installed.
- 2). The schedule to achieve the clean-up levels off-site depend on 3 variables a) the amount of time it takes to develop and implement an improved detection monitoring system and make the data available on the USEPA website; b) whether or not the Phase I wells remove the off-site methane within 5-6 months of implementation; and, c) whether or not the methane contamination near the school is coming from the site, and if so, the recommended remediation strategy. Various scenarios and associated schedules follow:
 - A) Earliest completion date Spring 2009 This assumes: 1) the RPs quickly implement adequate monitoring on the west side to ensure methane is not migrating off-site in excess of 50% of the LEL and the information is made available to the public via the USEPA Mallard Lake website; 2) Phase 1 implementation for 5-6 months, and confirmation data indicating the methane clean-up levels off-site (50% of the LEL, or lower) have been achieved; 3) the landfill is not the source of methane NE of the landfill near the school.
 - B) Fall 2009 (or later) completion date This assumes: 1) a Phase 2 (involving additional extraction wells and/or hard-piping of extracted off-site gas to gas to energy plant for treatment) is necessary

and/or 2) the contamination NE of the site near the school is associated with the landfill and remediation is necessary to remove this subsurface methane contamination.

Transition Issues

- 1. Regardless of the schedule to achieve and maintain the methane clean-up levels, USEPA will require the facility to continue verification gas perimeter monitoring for 12 months under the (AOC). If additional locations of methane exceedances are detected near residential locations or the school, and are attributable to the Mallard Lake Landfill, USEPA will require the facility to achieve the clean-up levels under the AOC. The USEPA verification monitoring requirements will use the same perimeter sampling points as the long-term perimeter monitoring plan required under the current State permit. The only differences will be additional sampling locations on the west side of the site, more frequent monitoring and data submittal, and the data being made available to the public. Overall this monitoring program and reporting frequency is structured to enhance and expand on the existing permit requirements and address the concerns raised by residents at the recent public meeting. USEPA is interested in the transitioning the perimeter monitoring requirements into the IEPA permits once the clean-up levels are reached under and in the vicinity of the residential areas and schools, and the threat of imminent and substantial endangerment has ended.
- 2. Preliminary data indicates that methane is migrating from the Mallard North Landfill, which is enrolled in the IEPA voluntary site clean-up program. As Mallard North Landfill may be the source of contamination in ML-6, located northeast of the site close to the school, USEPA requests all information on Mallard North be sent to Steve Faryan.

allowed North Lave Files where is italin process

· Weddy Schedule · People Rus · Molland Ipolate

Summary of Completion Details for Selected Probes ML-6 Investigation Area Mallard Lake Landfill STS Project No. 200704805

Well	Elevation of Top of PVC (ft MSL)	Top of Screen (ft bgs)	Bottom of Screen (ft bgs)	Elevation of Ground Surface (ft MSL)	Elevation of Top of Screen (ft MSL)	Elevation of Bottom of Screen (ft MSL)	
MW-204S	776.41	17.9	32.4	774.4	756.5	742.0	
MW-204D	777.23	40.2	50.2	774.4	734.2	724.2	
MW-204ES	Unknown	3.4	18.4	774.4	771.0	756.0	
MW-205	785.8	25.7	40.7	783.6	757.9	742.9	
MW-205ES	Unknown	10.6	25.6	783.6	773	758	
ML-6	792.56	48	53	792.95	744.95	739.95	
ML-6s	792.00	5.2	15.2	792.5	787.3	777.3	
ML-6i ¹	792.00	21	41	792.5	771.5	751.5	
ML-8	Unknown	21.0	41.0	792	771	751	
ML-9	Unknown	25.0	45:0	796	771	751	
ML-10	Unknown	27.0	47.0	798	771	751	
ML-11	Unknown	19.0	39.0	790	771	751	
ML-12	Unknown	20.0	40.0	791	771	751	
ML-13 ²	Unknown	7	27	777	770	750	
ML-14	Unknown	28.0	48.0	799	771	751	
ML-15 ²	Unknown	6	26	776	[†] 770	750	
ML-16 ²	Unknown	20	40	790	770	750	
ML-17	Unknown	20	40	790	770	750	
ML-18	Unknown	16.0	36.0	786	770	750	
GPT-7 ¹	767.7	3.5	13.5	768	764.5	754.5	
GPT-8 ¹	765.7	4.3	14.3	766	761.7	751.7	
GPT-9 ²	766.7	30	40	767	737	727	
GPT-10 ²	769.7	30	40	770	740	730	
GPT-10S ²	769.7	5	15	770	765	755	
G54S	785.38	42	47	782.28	740.28	735.28	
24 probes	Total Lineal	Ft.	705	-	•	-	

Drilling this investigation

Notes:

- 1. Probes are installed but have not been surveyed. Elevations are approximate.
- 2. Probes are not yet installed. Elevations are approximate
- 3. Approximate West Branch of DuPage River Elevation 764 ft MSL
- 4. Base of Mallard Lake Landfill (i.e., Maximum Sump Depth) = ± 740 ft MSL (Refer to Nature and Extent Report Drawing 1)
- 5. Anticipated screen intervals are an approximation based on probe ML-6i depth, actual screen placement will be determined based on observed geological conditions and results of field gas screening